

SUMMER – 19 EXAMINATION

Subject Name: **Advanced Manufacturing Process**

Model Answer

Subject Code:

17527

Important Instructions to examiners:

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more Importance (Not applicable for subject English and Communication Skills).
- 4) While assessing figures, examiner may give credit for principal components indicated in the figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case of some questions credit may be given by judgement on part of examiner of relevant answer based on candidate's understanding.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.

Q. No.	Sub Q. N.	Answer	Marking Scheme
1a		Attempt any THREE of the Following	12
	(i)	Draw neat sketch of wire cut EDM. Explain the working Principle.	04
	Ans	<p>Working Principle: The basic mechanism of metal removal in WEDM is identical to that in die sinking type EDM. Instead of moving electrode, the electrode in this process is a moving wire of CU or brass. A vertically oriented wire is fed into the work piece continuously travelling from a supply spool to take a spool, so that it is continuously renewed , since it will get worn out during the process</p> <p style="text-align: center;">Figure: Wire Cut EDM</p>	<p>02 Marks For Working Principle & 02 Marks For Neat Labelled Sketch</p>
	(ii)	State and explain any four process parameters of Laser Beam Machining.	04



	Ans	<p>Process parameters of Laser Beam Machining:</p> <p>a) Intensity of laser beam: By focusing a laser beam in a spot of 0.01 m^2, it can give power density of 100000 kW/cm^2. The focused beam radius is directly proportional to the laser wavelength and the focal length.</p> <p>b) Pulse duration of laser beam: The pulse durations about 6 to 12 pulse/ min. It depends upon the application to be performed like welding, drilling, cutting etc.</p> <p>c) Focal length: It is the distance between laser beam and the workpiece. If the laser is very close to the workpiece the divergence of the beam occurs for small focal length in the metal cutting. : It is important in drilling operation.</p> <p>d) Mode of laser operation : It can operate in continuous mode and pulsed wave mode</p>	<p>02 Marks For List of four Parameters & 02 Marks For Their Explanation</p>																								
	(iii)	Differentiate between open loop and closed loop control system	04																								
	Ans	<table border="1"> <thead> <tr> <th data-bbox="224 737 402 774">Parameter</th> <th data-bbox="402 737 873 774">Open loop</th> <th data-bbox="873 737 1354 774">Closed loop</th> </tr> </thead> <tbody> <tr> <td data-bbox="224 774 402 812">Design</td> <td data-bbox="402 774 873 812">Simple</td> <td data-bbox="873 774 1354 812">Complex</td> </tr> <tr> <td data-bbox="224 812 402 850">Feedback</td> <td data-bbox="402 812 873 850">No feedback element</td> <td data-bbox="873 812 1354 850">Feedback system is present</td> </tr> <tr> <td data-bbox="224 850 402 997">Input</td> <td data-bbox="402 850 873 997">The input is directly given to the MCU</td> <td data-bbox="873 850 1354 997">The input and feedback signal is given to the comparator which sends the required signal to the MCU</td> </tr> <tr> <td data-bbox="224 997 402 1073">Output</td> <td data-bbox="402 997 873 1073">The output may not be as desired</td> <td data-bbox="873 997 1354 1073">The output given is exactly as desired</td> </tr> <tr> <td data-bbox="224 1073 402 1148">Time</td> <td data-bbox="402 1073 873 1148">Time required for processing is less</td> <td data-bbox="873 1073 1354 1148">Time required for processing is More</td> </tr> <tr> <td data-bbox="224 1148 402 1186">Cost</td> <td data-bbox="402 1148 873 1186">Cheaper</td> <td data-bbox="873 1148 1354 1186">Expensive</td> </tr> <tr> <td data-bbox="224 1186 402 1262"></td> <td data-bbox="402 1186 873 1262"></td> <td data-bbox="873 1186 1354 1262"></td> </tr> </tbody> </table>	Parameter	Open loop	Closed loop	Design	Simple	Complex	Feedback	No feedback element	Feedback system is present	Input	The input is directly given to the MCU	The input and feedback signal is given to the comparator which sends the required signal to the MCU	Output	The output may not be as desired	The output given is exactly as desired	Time	Time required for processing is less	Time required for processing is More	Cost	Cheaper	Expensive				<p>01 Mark Each Any 4 Points</p>
Parameter	Open loop	Closed loop																									
Design	Simple	Complex																									
Feedback	No feedback element	Feedback system is present																									
Input	The input is directly given to the MCU	The input and feedback signal is given to the comparator which sends the required signal to the MCU																									
Output	The output may not be as desired	The output given is exactly as desired																									
Time	Time required for processing is less	Time required for processing is More																									
Cost	Cheaper	Expensive																									
	(iv)	State the advantages and limitations of Broaching Machine.	04																								
	Ans	<p>Advantages (Any Four)</p> <ol style="list-style-type: none"> 1) Broaching is faster than other machining operations 2) It enables higher rate of production with more accuracy & finish than other machining operations 3) It has longer tool life than other cutting tools. Tool cost per job is low 4) Both roughing & finishing operations are done by single tool 5) Interchangeable components can be produced at much faster rate in Broaching 6) Broaching operation does not require highly skilled operator <p>Limitations: (Any Four)</p> <ol style="list-style-type: none"> 1) High tool cost 2) Very large work pieces cannot be machined 3) The surfaces to be broach cannot have an obstruction 4) Large amount of stock (Material removal) cannot be removed 5) Work pieces must be rigidly supported 	<p>01/2 Mark for Each Advantage</p> <p>and</p> <p>01/2 Mark for Each Limitation</p>																								
1b		Attempt any ONE of the following	06																								
	(i)	Draw the set up for Abrasive Jet Machining. Explain the working principle and its process parameters.	06																								

Ans Abrasive Jet Machining:




Figure: Set up of Abrasive Jet Machining

Working Principle:

In Abrasive Jet Machining (AJM), usually air is directly taken from atmosphere, cleaned it and compressed it to a high pressure with the help of compressor. Loose abrasive particles having predefined average size are mixed with this pressurized gas in certain proportion (mixing ratio) and the mixture is then allowed to strike the work surface in the form of jet at a particular incident angle at very high velocity. A nozzle converts the hydraulic energy (pressure) of the jet-abrasive mixture into kinetic energy (velocity). After cutting action, grits leave the machining zone, which are then collected and disposed safely (usually, abrasive grits cannot be reused as grits lose sharpness after first impact).

Process Parameters:

(1) Abrasive Mass Flow Rate:

Mass flow rate of the abrasive particles is a major process parameter that influences the metal removal rate in abrasive jet machining. In AJM, mass flow rate of the gas (or air) in abrasive jet is inversely proportional to the mass flow rate of the abrasive particles. Due to this fact, when continuously increasing the abrasive mass flow rate, Metal Removal Rate (MRR) first increases to an optimum value (because of increase in number of abrasive particles hitting the workpiece) and then decreases. However, if the mixing ratio is kept constant, Metal Removal Rate (MRR) uniformly increases with increase in abrasive mass flow rate.

(2) Nozzle Tip Distance:

Nozzle Tip Distance (NTD) is the gap provided between the nozzle tip and the workpiece. Upto a certain limit, Metal Removal Rate (MRR) increases with increase in nozzle tip distance. After that limit, MRR remains constant to some extent and then decreases. In addition to metal removal rate, nozzle tip distance influences the shape and diameter of cut. For optimal performance, a nozzle tip distance of 0.25 to 0.75 mm is provided.

(3) Gas Pressure:

Air or gas pressure has a direct impact on metal removal rate. In abrasive jet machining, metal removal rate is directly proportional to air or gas pressure.

(4) Velocity of Abrasive Particles:

Whenever the velocity of abrasive particles is increased, the speed at which the abrasive particles hit the workpiece is increased. Because of this reason, in abrasive jet

02
Marks
for
Sketch
02
Marks
for
Working
Principle
&
01
Marks
for
List
of
Process
Parameters
&
01
Mark
for
Explanation
of
Any
One
Parameter

machining, metal removal rate increases with increase in velocity of abrasive particles.

(5) Mixing Ratio:

Mixing ratio is a ratio that determines the quality of the air-abrasive mixture in Abrasive Jet Machining (AJM). It is the ratio between the mass flow rate of abrasive particles and the mass flow rate of air (or gas). When mixing ratio is increased continuously, metal removal rate first increases to some extent and then decreases.

(6) Abrasive Grain Size:

Size of the abrasive particle determines the speed at which metal is removed. If smooth and fine surface finish is to be obtained, abrasive particle with small grain size is used. If metal has to be removed rapidly, abrasive particle with large grain size is used.

(ii) Explain with sketch axis identification for CNC lathe and VMC

06

Ans **CNC Lathe:**




Figure: Axis Identification for CNC Lathe

In lathe only two axes are there;

Z axis--- The axis of rotation of the workpiece is specified by Z axis

X axis--- The radial location of the cutting tool is represented by X axis

VMC:




Figure: Axis Identification for CNC Lathe

(1) Z axis---1) Main spindle axis.

In VMC Z(+ve) means cutter movement upward.

In VMC Z(-ve) means cutter movement downward.

(2) X axis---1) Horizontal –work holding device.

X (+ve) means as being to the right when looking from the spindle towards column.

X (-ve) means as being to the left when looking from the spindle towards column.

(3) Y axis—It is perpendicular to X and Z axes. It indicates cross travel of the work table

*02
Marks
for
Each
Neat
Labelled
Sketch
&
And
01
Mark
for
its
Explanation*



	(a)	State any four reasons for the need of non-traditional machining processes.	04
Ans		Need of Non-Traditional Machining Processes: (Any four) 1) Replacement of existing manufacturing methods by more efficient & quicker methods. 2) Achievement of higher accuracies & quality of surface finish 3) Adaptability of cheaper materials in place of costlier one. 4) To do machining operations for “Hard to machine” materials like tungsten, uranium 5) To do machining operations on intricate & thin workpieces economically. 6) Development of new materials requires new methods	<i>01 Mark for Each Point</i>
	(b)	Define Part Programming. Give a word address format for writing an instruction along with the meaning of each term.	04
Ans		Part Program: Part programming – Part program defined as the way in which the blocks of instructions are planned and written such that after its execution on the CNC machine the required shape is obtained on the work piece in minimum possible time. OR Part program is a set of instructions the machine tool about the processing steps to be performed the manufacture of component. Word Address Format For Example:- N001 G01 X2.0 Y5.5 Z-3.0 F100; N002 M06 T0101; Meaning N001 – Block No. 001 G01 – Preparatory Function(Linear Interpolation) X2.0, Y5.5, Z-3.0 – XYZ Axis Movement. F100 – Feed Rate in mm/min M06 – Miscellaneous Function(Tool Change) T0101 – Tool No. 01 with offset No 01 ; - End of Block	<i>01 Mark for Definition & 03 Marks for Suitable Example and its Appropriate Meaning</i>
	(c)	Explain with neat sketch Up Milling and Down Milling	04
Ans		Up milling: it is the conventional milling process which is most commonly used. In this, the material is removed by the cutter which is rotating against the direction of travel of the work piece. As shown in fig., the thickness of the chip in the up milling is minimum at the beginning of the cut and it reaches maximum when the cutter terminates. As the chip thickness per tooth is not uniform, the cutting force in upmilling increases from zero to maximum. The cutting force is directed upwards and it tends to lift the work from the fixture. Due to this, difficulty is experienced in pouring coolant just on the cutting edge from the chip begins. As the cutter progresses, the chip gets accumulated at the cutting zone which spoils the machined surface. The surface milled by up milling is slightly wavy as the cutter teeth do not begin their cut as soon as they touch the work surface.	<i>01 Mark for Each Figure And Explanation</i>




Figure: Up Milling

Down Milling:

It is also known as climb milling. In this, material is removed by the cutter which is rotated in the same direction of travel of the work piece. As shown in fig., the thickness of the chip is maximum when the tooth begins the cut and it reduces to minimum when the cut terminates. The cutter tooth starts removing the metal immediately on reaching the work piece, without sliding. The cutting force in down milling is maximum when the tooth begins its cut and is minimum when the tooth leaves the work. Here the chips are disposed off easily and do not interfere with the work. Fixture design is easier as the cutting force tries to seat the work firmly in work holding devices. Coolant can be poured directly at the cutting zone. This results in improved surface finish. If there is any backlash in feed screw, it causes vibrations and damages work surface.




Figure: Down Milling.

(d) State and explain various indexing methods.

04

Ans (1) Plain or Simple Indexing.

In plain indexing the dividing head spindle is moved by turning the index crank. As the shaft carrying the crank has a single threaded worm which mesh with the worm gear having 40 teeth, 40 turns of the crank are necessary to rotate the index head spindle though one revolution. To facilitate indexing to fractions of a turn, index plates are used to cover practically all numbers. Index plates with circles of holes are as follows:-

- Plate No. 1 – 15, 16, 17, 18, 19, 20
- Plates No. 2 – 21, 23, 27, 29, 31, 33.
- Plate No. 3 – 37, 39, 41, 43, 47, 49.

With the three index plate supplied, simple indexing can be used for all divisions up to 50, even numbers up to 100 except 96. The formula for index crank movement is given below:-

Index Crank Movement = $40/N$ where, N= number of divisions required.

02
Marks
for
List
of
Indexing
Method
&
02
Marks
Explanation of
Any
One




Figure: Plain or Simple Indexing

(2) Universal Dividing Head:

The worm gear has 40 teeth and the worm has simple thread. Crank is directly attached with the worm. If we revolve crank by 40 revolutions the spindle attached with worm gear will revolve by only one revolution and one complete turn of the crank will revolve the spindle only by $1/40^{\text{th}}$ revolution (turn). In order to turn the crank precisely a fraction of a revolution, an indexing plate is used. An indexing plate is like a circular disc having concentric rings of different number of equally spaced holes. Normally indexing plate is kept stationary by a lock pin. A spring loaded pin is fixed to the crank which can be fixed into any hole of indexing plate. The turning movement of the work piece is stably controlled by the movement of crank.




Figure: Universal Dividing Head

(3) Optical Dividing Head:

It is used for precise angular indexing during machining. The mechanism comprises a worm gear which is keyed to the spindle and may be rotated by a worm. A circular glass scale graduated in 10 division is rigidly mounted on the worm wheel. Any movement of the spindle effected by rotating the worm is read off by means of a microscope fitted on the dividing head body, the eye piece has a scale having 60 divisions & each division is equivalent to $1'$ movement of circular scale




Figure: Optical Dividing Head

(e) State difference between dielectric fluid and electrolyte

04

Ans

S. N.	Dielectric Fluid	Electrolyte
1	It is used as a conducting medium in EDM	It is used as a conducting medium in ECM
2	Tool wear takes place in dielectric fluid	The electrolyte is selected in such a way that there is no tool wear.
3	It act as a conductor and insulator both.	It always provide passage for the supply of electricity.
4	It may or may not be corrosive in nature.	It should be non-corrosive in nature.

01
Mark
Each
for
Any
Four
Points

3 a Explain working of Plasma Arc Machining. State Advantages, Disadvantages and Application

08

(03 Marks for Working, 02 Marks For Sketch & 01 Mark For Each Advantages, disadvantages and Application)

Plasma Arc Machining:

Plasma-arc machining (PAM) is a metal removal process in which metal is removed by directing high about 11000 to 30000 degree centigrade ionized gas on the work piece. The principle PAM is shown in the figure. In this process, plasma torch is used in which a volume of a gas such as H₂,N₂,O₂ is passed through a small chamber in which high frequency spark is maintained between cathode and anode. The plasma jet melts the work piece material. The depth of hat zone depends on the work material, its thickness and cutting speed.




Figure: Plasma Arc Machining Process

3
Marks
for
Working,
02
Marks
For
Sketch
&
01
Mark
For
Each

Advantages of PAM:

1. High speed of cutting e.g. 6 mm mild steel plate can be cut at a speed of 3 m/min.
2. Equally effective on any metal regardless its hardness
3. Smooth cuts free from contaminants are obtained in the process.
4. There is no contact between tool and workpiece
5. It is three to eight times faster than oxy fuel cutting
6. Profile cutting of stainless steel can be very easily done by this process

Disadvantages of PAM:

1. Due to high heat, metallurgical change on the workpiece surface
2. Safety precautions are necessary for the operator and those in nearby working area
3. It increases cost of process
4. On the thicker material it will lead noise, fume and arc glare hence water cooling is needed.

Applications of PAM:

1. Cutting Alloy Steels, Stainless Steels, Aluminium and its alloys
2. Used for turning and milling of difficult to machine materials
3. Used for removing of gates and risers from a casting.
4. Used in underwater operations like, in shipyards, chemical industries, nuclear power plant, etc.
5. Used for cutting of hot extrusions dies.


*Advantages,
Disadvantages
and
Application*

b Write a part program for milling a given component as shown in fig. no 1. The endmill cutter diameter is 10mm. Use feed rate as 100mm/min and spindle speed as 1000rpm. Assume suitable data wherever necessary.

08

*(02 Marks for Coordinates and 06 Marks for Correct Program)
[Note Explanation of codes not necessary]*

Point	X	Y	Z
P0	0.0	0.0	5.0
P1	20.0	90.0	5.0
P2	20.0	90.0	-5.0
P3	60.0	50.0	-5.0
P4	80.0	50.0	-5.0
P5	80.0	50.0	5.0



*02 Marks
for
Coordinates /
points*

Program:



		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">Block No</th> <th style="width: 40%;">CNC Codes Used</th> <th style="width: 50%;">Explanation of Codes</th> </tr> </thead> <tbody> <tr> <td></td> <td>O1234;</td> <td>Program No.</td> </tr> <tr> <td>N1</td> <td>G28 U0.0 V0.0 W0.0 ;</td> <td>Return to Reference Position</td> </tr> <tr> <td>N2</td> <td>M03 M08 S1000;</td> <td>Spindle Start Clockwise with 1000 RPM, Coolant ON.</td> </tr> <tr> <td>N3</td> <td>G90G21G94;</td> <td>Absolute Programming, Metric Mode, Feed in mm/min</td> </tr> <tr> <td>N4</td> <td>G00 X0.0 Y0.0 Z5.0;</td> <td>Move End Mill Tool of Diameter 10mm to Point P0</td> </tr> <tr> <td>N5</td> <td>G00 X20.0 Y90.0;</td> <td>Move End Mill Tool to Point P1</td> </tr> <tr> <td>N6</td> <td>G01 Z -5.0 F100;</td> <td>Move End Mill to Point P2 with feed of 100mm/min i.e. 5mm depth of cut below the surface of workpiece.</td> </tr> <tr> <td>N7</td> <td>G02 X60.0 Y50.0;</td> <td>Move the tool to Point P3 in clockwise Circular Interpolation</td> </tr> <tr> <td>N8</td> <td>G03 X80.0 Y50.0;</td> <td>Move the tool to Point P4 in Counter clockwise Circular Interpolation</td> </tr> <tr> <td>N9</td> <td>G01 X80.0 Y50.0 Z5.0;</td> <td>Move tool to Point P5 i.e. 5 mm above the surface of workpiece</td> </tr> <tr> <td>N10</td> <td>G28 U0.0 V0.0 W0.0;</td> <td>Return to Reference Position</td> </tr> <tr> <td>N11</td> <td>M05 M09;</td> <td>Spindle Stop, Coolant Stop</td> </tr> <tr> <td>N12</td> <td>M30;</td> <td>End of the Program and reset.</td> </tr> </tbody> </table>	Block No	CNC Codes Used	Explanation of Codes		O1234;	Program No.	N1	G28 U0.0 V0.0 W0.0 ;	Return to Reference Position	N2	M03 M08 S1000;	Spindle Start Clockwise with 1000 RPM, Coolant ON.	N3	G90G21G94;	Absolute Programming, Metric Mode, Feed in mm/min	N4	G00 X0.0 Y0.0 Z5.0;	Move End Mill Tool of Diameter 10mm to Point P0	N5	G00 X20.0 Y90.0;	Move End Mill Tool to Point P1	N6	G01 Z -5.0 F100;	Move End Mill to Point P2 with feed of 100mm/min i.e. 5mm depth of cut below the surface of workpiece.	N7	G02 X60.0 Y50.0;	Move the tool to Point P3 in clockwise Circular Interpolation	N8	G03 X80.0 Y50.0;	Move the tool to Point P4 in Counter clockwise Circular Interpolation	N9	G01 X80.0 Y50.0 Z5.0;	Move tool to Point P5 i.e. 5 mm above the surface of workpiece	N10	G28 U0.0 V0.0 W0.0;	Return to Reference Position	N11	M05 M09;	Spindle Stop, Coolant Stop	N12	M30;	End of the Program and reset.	<p><i>and</i> <i>06 Marks</i> <i>for</i> <i>Correct</i> <i>Program</i></p>
Block No	CNC Codes Used	Explanation of Codes																																											
	O1234;	Program No.																																											
N1	G28 U0.0 V0.0 W0.0 ;	Return to Reference Position																																											
N2	M03 M08 S1000;	Spindle Start Clockwise with 1000 RPM, Coolant ON.																																											
N3	G90G21G94;	Absolute Programming, Metric Mode, Feed in mm/min																																											
N4	G00 X0.0 Y0.0 Z5.0;	Move End Mill Tool of Diameter 10mm to Point P0																																											
N5	G00 X20.0 Y90.0;	Move End Mill Tool to Point P1																																											
N6	G01 Z -5.0 F100;	Move End Mill to Point P2 with feed of 100mm/min i.e. 5mm depth of cut below the surface of workpiece.																																											
N7	G02 X60.0 Y50.0;	Move the tool to Point P3 in clockwise Circular Interpolation																																											
N8	G03 X80.0 Y50.0;	Move the tool to Point P4 in Counter clockwise Circular Interpolation																																											
N9	G01 X80.0 Y50.0 Z5.0;	Move tool to Point P5 i.e. 5 mm above the surface of workpiece																																											
N10	G28 U0.0 V0.0 W0.0;	Return to Reference Position																																											
N11	M05 M09;	Spindle Stop, Coolant Stop																																											
N12	M30;	End of the Program and reset.																																											
c	i	Differentiate between pull broach and push broach	04																																										
	Ans	<p>(Any four Points = 01 Mark each)</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">S. N.</th> <th style="width: 45%;">Pull Broach</th> <th style="width: 50%;">Push broach</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>It is designed to pull through the work piece by a special press.</td> <td>It is designed to push through the work piece by a special press.</td> </tr> <tr> <td>2</td> <td>Broach is entirely in tension and is long slender.</td> <td>Because of the tendency to bend under compressive loads, push broach is short and stocky.</td> </tr> <tr> <td>3</td> <td>It has large no. of teeth and more stock can be removed for each pass.</td> <td>It has fewer teeth on the broach and less material is removed for each pass.</td> </tr> <tr> <td>4</td> <td>Material is removed in thick layers by each tooth only from part of work surface</td> <td>Holes are machined by push broaches only for sizing.</td> </tr> <tr> <td>5</td> <td>Widely used for external broaching.</td> <td>Widely used for internal broaching.</td> </tr> <tr> <td>6</td> <td>It has progressive cut teeth.</td> <td>It is solid type.</td> </tr> </tbody> </table>	S. N.	Pull Broach	Push broach	1	It is designed to pull through the work piece by a special press.	It is designed to push through the work piece by a special press.	2	Broach is entirely in tension and is long slender.	Because of the tendency to bend under compressive loads, push broach is short and stocky.	3	It has large no. of teeth and more stock can be removed for each pass.	It has fewer teeth on the broach and less material is removed for each pass.	4	Material is removed in thick layers by each tooth only from part of work surface	Holes are machined by push broaches only for sizing.	5	Widely used for external broaching.	Widely used for internal broaching.	6	It has progressive cut teeth.	It is solid type.	<p><i>Any four</i> <i>Points =</i> <i>01 Mark each</i></p>																					
S. N.	Pull Broach	Push broach																																											
1	It is designed to pull through the work piece by a special press.	It is designed to push through the work piece by a special press.																																											
2	Broach is entirely in tension and is long slender.	Because of the tendency to bend under compressive loads, push broach is short and stocky.																																											
3	It has large no. of teeth and more stock can be removed for each pass.	It has fewer teeth on the broach and less material is removed for each pass.																																											
4	Material is removed in thick layers by each tooth only from part of work surface	Holes are machined by push broaches only for sizing.																																											
5	Widely used for external broaching.	Widely used for internal broaching.																																											
6	It has progressive cut teeth.	It is solid type.																																											
	ii	Draw a nomenclature of a plain milling cutter. Label all the elements.	04																																										
	Ans	(Sketch = 02 Marks Labelling = 02 Marks)																																											




Figure : Plain Milling Cutter

Sketch =02
Marks
Labelling =
02 Marks

4 a Attempt any THREE of the following

12

i Explain with neat sketch gear hobbing process

04

Ans (02 Marks For Sketch & 02 Marks For Explanation)




Figure: Gear Hobbing

In this process of gear generating a tool is used known as hob. Hob teeth are shaped to match the tooth space and are interrupted with grooves to provide cutting surfaces. It rotates about an axis normal to that of the gear blank, cutting into the rotating blank to generate the teeth as shown in figure.

It is the most accurate of the roughing processes since no repositioning of tool or blank is required and each tooth is cut by multiple hob-teeth, averaging out any tool errors. Excellent surface finish is achieved by this method and it is widely used for production of gears.

02 Marks
For Sketch
&
02 Marks
For
Explanation

ii What is gear shaving? Explain with sketch



04

Ans (02 Marks for Explanation and 02 Marks for figure)

Gear Shaving Process:

Gear shaving process can be linear or rotary. In the linear type rack type cutter is used. While rotary method employs a pinion cutter. The cutter teeth are serrated to form a series of cutting edges. To obtained relative sliding action between the tooth profile the work gear and shaving cutter are set up in the gear shaving machine with cross axes.

02 Marks
for
Explanation
and
02 Marks

	<p>Due to the sliding action very small amount of material from the gear tooth is removed and finished profile surface is obtained.</p>  <p style="text-align: center;">Figure: Gear Shaving Tool with Serration</p>	<i>for figure</i>
iii	Explain wheel dressing and truing	04
Ans	<p>(02 Marks for Wheel Dressing and 02 Marks for Wheel Truing) [Note: Sketch is not Compusary]</p> <p>Dressing of Wheel Dressing: Dressing removes loading and breaks away the glazed surface so that sharp abrasive particles are again presented to work. A common type of star dresser is used to dress the wheel. The dresser is held against the wheel and moved across the face of revolving wheel. Dressing is done to regain grinding wheels cutting capability. The dressing improves the surface finishing obtained while grinding. It is carried out where high degree of surface finishing is desired.</p> <p>Truing of Grinding Wheel Truing is the process of changing the shape of grinding wheel as it becomes worn from an original shape owing to the break-away of the abrasive and bond. This is done to make wheel true and concentric to the bore. Truing and dressing are done from the same tool but not for the purpose. The truing can be done with the help of diamond tool but the feed rate must not exceed 0.02 mm otherwise grooves may be cut on the wheel.</p>  <p style="text-align: center;">Figure Dressing and Truing of Grinding Wheel</p>	<p>02 Marks for Wheel Dressing and 02 Marks for Wheel Truing</p>
iv	What information is collected in a maintenance record	04
Ans	<p>(02 Marks For Importance of Maintenance Record and 02 Marks Details of any one Record)</p> <p>Importance of Maintenance Record: Maintenance records are the various documents of maintenance activities carried out by staff of the maintenance section. These documents are used for improvements as well as to get the history of maintenance of a particular machine or equipment. The maintenance records include following reports.</p> <ol style="list-style-type: none"> 1. Machine History Card. 2. Preventive Maintenance Chart. 3. Break Down Report. 	

By using these previous record and its analysis it is easy for fast decision making when faults occur in the machine.

Machine History Card

Name of company : _____ Section : _____
Machine No : _____
Machine Name : _____ Make : _____

Date	Nature of fault	Action	Lost hours	Lost in Quantity	Remark	Sign

Checked by _____ Manager (Maintenance)

Preventive Maintenance Chart

- Company Name : _____
- Department /Section : _____
- Name of machine : _____ Maintenance staff : _____

Sr. No	Machine Part	Check for	Status required	Status observed	Action	Remark

Checked by _____ Approved by _____

Breakdown Maintenance Chart

Company Name : _____ Name of Machine : _____
Department Section : _____ Maintenance Staff: _____

Sr.No	Name of defective part	Action	Repair details	Breakdown			
				Date	Time	Date	Time

02 Marks
For
Importance
of
Maintenance
Record

and

02 Marks

Details
of
any
one
Record

b Attempt any ONE of the following

i Draw a labeled sketch of column and knee type milling machine. State function of any four elements.

Ans (02 Marks for Sketch & Labels and 01 Mark each for function of any four elements)




Figure : Column and Knee Type Milling Machine

02 Marks
for
Sketch
&
Labels
and
01 Mark each
for
function
of any four
elements



		<p>1) Base: To support all the parts of milling machine.</p> <p>2) Column: To support Spindle and drive mechanism.</p> <p>3) Knee: Can be moved vertically up and down on column by using elevating screw</p> <p>4) Over-Arm: To support other end of the arbor.</p> <p>5) Saddle: To move horizontally towards the column and away from column.</p> <p>6) Table: To move towards the left and right of operator and to clamp the work-piece with T- slots on it.</p> <p>7) Spindle: To hold rotary milling cutter.</p>	
	ii	<p>How well you specify a grinding wheel? Explain with a suitable example.</p>	
Ans	<p><i>(Correct Answer = 06 Marks)[Note: Figure is not Necessary]</i></p> <p>Wheel Specification:</p> <div style="text-align: center;"> </div> <p style="text-align: center;">Figure : Grinding Wheel</p> <p>450 X 60 X 101.6 ROS (200 X 20)W A 46 K 5 V 17</p> <p>D= 450 – Outer Diameter of Grinding Wheel in mm T= 60 – Thickness of Grinding Wheel in mm H= 101.6– Bore Diameter of Grinding Wheel in mm W- Prefix. (Manufacturer’s Symbol)(Optional) ROS – Recess One Side of Diameter P = 200mm and F = 20mm A - Abrasive type is Al₂O₃. 46- Abrasive Grain size is Medium. K- Grade is Medium. 5 – Structure is dense V – Type of Bond used is Vitrified. 17 - Suffix. (Manufacturer’s Symbol)(Optional)</p>		<p><i>Correct Answer = 06 Marks</i></p>
5	<p>Attempt any FOUR of the following</p>		
a	<p>Classify Boring machines. State different types of tools used</p>		
Ans	<p>Classification of Boring Machines</p> <p>1) Horizontal boring machine</p> <p style="margin-left: 20px;">a) Table type b) Floor type c) Planer type d) Multiple type</p> <p>2) Vertical boring machine</p> <p style="margin-left: 20px;">a) Vertical turret lathe b) Standard vertical boring machine</p>		<p>½ Mark each for 4 correct classification</p>

	<p>3) Precision boring machine 4) Jig boring machine a) Vertical milling type b) Planer type</p> <p>Different types of tools used [1] Boring by tool head [2] Boring by boring bar [3] Light Boring Tools [4] Forged Boring tools [5] Double ended boring tool [6] Counter boring tool [7] Multiple edge boring tool</p>	<p>½ Mark each for any 4 correct types</p>
<p>b Ans</p>	<p>State advantages and applications of turret lathe</p> <p>Advantages [1] More rigidity provided to the tool [2] Suitable for Larger and heavier loads [3] Larger works can be machined easily [4] Suitable for batch or mass production [5] More productive for quick engagement and over lapped functioning of the tools [6] Series of operations can be performed</p> <p>Applications [1] Suitable for heavy workpieces [2] It finds application in machining longer workpieces [3] More lengthwise movement allows it to machine for greater length [4] Used in mass production system</p>	<p>1 mark each for any 2 correct points</p> <p>1 mark each for any 2 correct points</p>
<p>c Ans</p>	<p>Explain gang milling and straddle milling</p> <p>Gang Milling:- The gang milling is the operation of machining several surfaces of a work piece simultaneously by feeding the table against number of cutters having same or different diameters mounted on the arbour of the machine. The method saves much machining time and its widely used in repetitive work. The cutting speed of gang of cutter is calculated from cutter of the large diameter.</p> <div data-bbox="548 1627 1036 1927" data-label="Diagram"> <p>The diagram illustrates the gang milling process. It shows a horizontal arbor with two cutters mounted on it. On the left is a 'Plain milling cutter' and on the right is a 'Side and face milling cutter'. Both cutters are in contact with a 'Workpiece' below them. The entire setup is labeled 'Gang milling'.</p> </div>	<p>2 Marks for explanation</p>

Figure:- Gang Milling

Straddle Milling:- The straddle is the operation of production of flat vertical surfaces on the both sides of the workpiece by using two side cutters by providing coller between them for spacing. The straddle milling is very commonly used to produce square or hexagonal surfaces.




Figure:- Straddle Milling

2 Marks for explanation

d What is centre less grinding? Explain any one with neat sketch

Ans Centreless grinding is a method of grinding exterior cylindrical, tapered and formed surfaces that are not held and rotated on centres.

The principle elements of the grinders are,

- 1) Grinding wheel
- 2) Work
- 3) Regulating wheel
- 4) Work rest

An angular adjustment of 0 to 10° is provided in the machine by tilting regulating wheel.

The actual feed can be calculated by,

$$S = \pi d n \sin \alpha$$

Where,

S= Feed in mm/min,

N = rpm

d= dia. Of regulating wheel,

α = angle of inclination if any




Figure: Centreless Grinding


Both the wheels are rotated in the same direction. The work rest is located between the wheels, the work is rest upon the work rest and together with regulating wheel fed forward, forcing the work against grinding wheel. The axial movement of the work past the grinding wheel is obtained by tilting regulating wheel at a slight angle from horizontal.


1 Mark for definition

2 Marks for explanation

&

1 Mark for diagram

e	<p>Explain the working principle of honing. State its applications</p>	
Ans	<p>Principle</p> <p>Honing is a grinding or a abrading process mostly finishing round holes by means of bonded abrasive stones called hones. Materials ranged from plastics, silver, aluminium, brass and cast iron can be honed easily.</p> <div style="text-align: center;">  </div> <p style="text-align: center;">Figure: Honing Tool</p> <p>Applications</p> <ol style="list-style-type: none"> 1) Finishing automobile crankshafts journals 2) Finishing round holes 3) Finishing hollow cylindrical parts 	<p>2 Marks for principle & 1 Mark each for 2 correct applications</p>
f	<p>What are different types maintenance? Give suitable example of each</p>	
Ans	<p>Types of Maintenance</p> <ol style="list-style-type: none"> 1) Preventive maintenance:- Cleaning, Lubrication, Replacement of consumables like belts, bearings, gaskets etc, Reconditioning 2) Predictive maintenance:- Changing of oil in car, replacement of bearing due to noise 3) Breakdown maintenance:- Machine tool failure on production floor 4) Corrective maintenance:- Replacement of chain due to noise, replacement of bearing due to failure 5) Scheduled maintenance:- Overhauling of machine tool, Servicing of motor bike 	<p>01 Mark each for any 4 correct point and Example</p>
6	<p>Attempt any FOUR of the following</p>	16
a	<p>Explain the concept of Dry run and Jog mode</p>	
Ans	<p>Dry Run</p> <p>A key that activates the dry run feature on a CNC machine. The dry run function checks a program quickly without cutting parts.</p> <p>A dry run (or a practice run) is a testing process where the effects of a possible failure are intentionally mitigated.</p> <p>Example:- An aerospace company may conduct a "dry run" test of a jet's new pilot ejection seat while the jet is parked on the ground, rather than while it is in flight.</p> <p>Objectives:-</p> <ol style="list-style-type: none"> 1) to verify the correctness of the setup with proven CNC programs 2) to find serious mistakes that still exist in the program 	<p>2 Marks for Explanation</p>

	<p>Jog Mode The area of the machine control that allows an operator to move a selected axis. Jog keys are often called axis direction keys. In JOG mode, the continuous movement of a tool in a direction along a selected axis. Jog mode is mostly used to travel the CNC machine table slide for movement of table along X-axis and Z-axis. CNC machine works manually like conventional machines.</p>	2 Marks for Explanation
<p>b Ans</p>	<p>Explain how a capstan lathe is different from a simple lathe It is production lathe used to manufacture any number of identical pieces in the minimum time. The capstan and turret lathe consists of a bed, all geared headstock and a saddle on which a four station tool post is mounted to hold four different tools. A series of operation can be perform such as turning, drilling, boring, reaming etc [1] The turret of capstan lathe is mounted on slides on the saddle [2] Less rigidity provided to the tool [3] High production rate as fast cut is possible</p>	4 Marks for explanation
<p>c Ans</p>	<p>Sketch and label basic parts of a horizontal broaching machine</p>  <p style="text-align: center;">Figure: Horizontal Broaching Machine.</p>	3 Marks for neat sketch & 1 Mark for Correct labeling
<p>d Ans</p>	<p>Enlist grinding wheel safety precautions Safety Precautions:- 1) Ensure proper mounting of wheel 2) Ensure fitting of wheel 3) Check Proper balancing 4) Check guarding arrangement on machine for wheel. 5) Check proper truing of grinding wheel</p>	1 Mark each for any 4 correct points

e Explain repair cycle analysis with a suitable example

Ans Repair Cycle Analysis

The repetitive performance of maintenance activities between two overhauling (inspection) is called as repair cycle analysis.

For maintenance planning repair cycle analysis is important.

Need of repair cycle analysis:

- It gives an idea about staff required.
- Number of small/minor repairs.
- Number of major repairs.
- Number of spare parts (quantity required for maintenance)




Figure: Repair Cycle Analysis

Example :- Repairing for Misalignment and noise of shaft in machine tool

Repair cycle analysis involves:

[1] Primary Inspection:-

Proper examination of the machine tool is carried to identify the problem. In this stage root cause of the problem can be found out such as which part creates the noise. Whether it shaft is misaligned due to bending or improper fitting in bearing?

[2] Small Repair-01:-

In this stage as per the problem complexity cleaning or lubrication, type of small repair is performed.

[3] Small Repair-02:

After repair one if the problem still exists another small repairs like alignment, proper assembly, nut and bolt tightening, lubrication is performed.

[4] Inspection:-

After small repair the machine tool is inspected for its performance.

[5]Major repair:-

If the small problem exists after small repair the major repair takes place like replacement of shaft or bearing is required.

[6] Inspection:

After major repair the inspection carried out for effective and efficient performance of that machine tool.

2 Marks for explanation

&

2 Marks for any correct Example